

CONVAIR SERVICE BULLETIN/LETTER INDEX

| 240D | | | |
|---|---|--------------------------------|---------------------|
| NUMBER | TITLE | MODEL | ISSUE DATE |
| ASB 600(240D)-82-004 CANCELLED | Inspection of Water/Methanol Lines | 240D | Nov 25/2004 |
| 340D | | | |
| NUMBER | TITLE | MODEL | ISSUE DATE |
| 640(340D)-32-016 | Inspection of MLG Axle Inner Surface | 340D | Feb 10/2005 |
| 640(340D)-82-004 CANCELLED | Inspection of Water/Methanol Lines | 340D | Nov 25/2004 |
| CV340 | | | |
| NUMBER | TITLE | MODEL | ISSUE DATE |
| SB CV340-24-001 | Obsolete Part numbers NS47E, NS47EK and ND47E | CV340 | Jul 2/2008 |
| SB 340-27-001 | Flight Controls – Elevator Trim Cable Routing – Placard Installation | CV340/440/640/580/5800 C-131 | Apr 24/2015 |
| ASB 340-32-001 | Nose Landing Gear (NLG) Upper Drag Strut Inspection at the Down-Latch Lever Attachment Location | CV340/440/640/580/5800 C-131 | Nov 28/2013 |
| SB 340-35-001 CANCELLED | Replacement of Oxygen Regulator | CV340 | Rev 2 - Feb 15/2012 |
| SB 340-35-002 | Oxygen Regulator and Altitude Gauge Protector Installation | CV340/440/640/580/5800 | Rev 3 - Apr 15/2019 |
| SB 340-35-003 | Oxygen Regulator and Altitude Gauge Protector Installation | CV580 SN 022/082/151/160 | Rev 2 – Apr 15/2019 |
| SB 340-52-001 | Exterior Doors – (Yoke Assembly) – Inspection | CV340/440/640/580/5800 C-131 | Apr 15/2016 |
| SB 340-53-001 | Nose Landing Gear (NLG) Beam Upper Chord Reinforcement | CV340/440/640/580/5800 | Dec 23/2013 |

CONVAIR SERVICE BULLETIN/LETTER INDEX

| | | | |
|---------------|---|-------------------------------------|-------------|
| SB 340-55-001 | LH and RH Elevator Skin and Bead Strip Visual Inspection | CV340/440/6 40/580/5800 C-131 | Nov 20/2014 |
| SB 340-55-003 | Stabilizers LH and RH Elevator Nose Rib Tee Visual Inspection | CV340/440/6 40/580/5800 C-131 | Nov 20/2014 |
| SB 340-57-001 | Inspection of Lower Wing Skin for Cracks Between WS 5 and WS 6 | CV340/440/6 40/580/5800 C-131 | Feb 12/2013 |
| SL 340-00-001 | Surrender of EASA Validated Convair 340/440 Aircraft Type Certificate A-220 | CV340/440 | Aug 28/2017 |
| SL 340-32-001 | MLG Actuator Rigging Placard | CV340/440/6 40/C-131 | Jun 18/2014 |
| SL 340-32-002 | NLG Down-Latch Rigging | CV340/440/6 40/580/5800 C-131 | Nov 20/2014 |

| CV440 | | | |
|-----------------------------------|---------------------------------|-------|---------------------|
| NUMBER | TITLE | MODEL | ISSUE DATE |
| SB 440-35-001 CANCELLED | Replacement of Oxygen Regulator | 440 | Rev 2 - Feb 15/2012 |

| CV580 | | | |
|-----------------------------------|---|------------------|---------------------|
| NUMBER | TITLE | MODEL | ISSUE DATE |
| SB CV580-24-001 | Obsolete Part numbers NS47E, NS47EK and ND47E | CV580 | Jul 02/2008 |
| SB 580-24-002 | Electrical Power Current Transformer Replacement | CV580/ CV5800 | Jul 30/2013 |
| SB 580-25-001 | NAV/GLS and VHF COMM Panels Modification | CV580 SN 002 | Sep 19/2011 |
| SB 580-27-002 | Rudder Torque Tube Coupling - Crack Inspection | CV580/CV58 00 | Jul 18/2018 |
| SB 580-35-001 CANCELLED | Replacement of Oxygen Regulator | CV580 | Rev 2 - Feb 15/2012 |
| SB 580-55-002 | Elevator Rear Spar Crack Inspection | CV580 | Rev 1 - Aug 28/2015 |
| SB 580-79-001 | Replacement of Cockpit Oil Quantity Indicator and Nacelle Oil Calibration Rheostats | CV580 | Sep 06/2012 |

CONVAIR SERVICE BULLETIN/LETTER INDEX

| | | | |
|-----------------------------------|---|-----------------|-------------|
| SB CV 580-80-001 | Replacement of Moisture Indicator Plug and Placard of Nitrogen Start System | CV580 | Dec 02/2010 |
| SL 580-00-001 | K052 Illustrated Parts Catalogue Distribution | CV580 | Oct 6/2018 |
| SL 580-24-001 | DC Generator Control Panel | CV580/580A/5800 | Nov 26/2012 |
| SL 580-31-001 | Tachometer Indicator | CV580/580A/5800 | Oct 10/2012 |
| SL 580-32-001 CANCELLED | NLG Wheel Assembly - Torque Flange Bolts | CV580/5800 | Feb 21/2017 |
| SL 580-57-001 | Corrosion Inspections | CV580/580A/5800 | Sep 11/2013 |
| SL 580-61-001 | Propeller Feather Switch | CV580/580A/5800 | Oct 05/2012 |
| SL 580-71-001 | QEC Quick Disconnects Modification | CV580 | Nov 24/2016 |
| SL 580-76-001 | Emergency Shutdown Switch | CV580/580A/5800 | Jul 22/2013 |

| CV580A | | | |
|-------------------|--|-----------------------------|-------------------|
| NUMBER | TITLE | MODEL | ISSUE DATE |
| SB K196-23-001 | Communication - VHF System - Antenna Replacement | CV580A SN 234/238/509 | Mar 31/2008 |
| SB K196-24-001 | Electrical Power - DC Generator System- Field Circuit Breaker Switch Guard | CV580A SN 238, 509 | Mar 23/2007 |
| SB K196-27-001 | Flight Controls - Indicated Angle of Attack System - Fail Indicator Lamp Rewire | CV580A SN 509 | Dec 01/2006 |
| SB K196-31-001 | Indicating/Recording Systems - Master Warning/Caution Circuits - Wiring Changes | CV580A SN 509 | Dec 01/2006 |
| SB K196-34-001 | Navigation - Electronic Standby Instrument System - ESIS on BATT lamp Installa- tion | CV580A SN 509 | Dec 01/2006 |
| SB CV 580A-80-001 | Replacement of Moisture Indicator Plug and Placard of Nitrogen Start System | CV580A | Dec 02/2010 |
| SL 580A-24-001 | DC Generator Control Panel | CV580/580A/ 5800 | Nov 26/2012 |

CONVAIR SERVICE BULLETIN/LETTER INDEX

| | | | |
|-------------------|--|---|---------------------|
| SL 580A-31-001 | Tachometer Indicator | CV580/580A/ 5800 | Oct 10/2012 |
| SL 580A-57-001 | Corrosion Inspections | CV580/580A/ 5800 | Sep 11/2013 |
| SL 580A-61-001 | Propeller Feather Switch | CV580/580A/ 5800 | Oct 05/2012 |
| SL 580A-76-001 | Emergency Shutdown Switch | CV580/580A/ 5800 | Jul 22/2013 |
| CV5800 | | | |
| NUMBER | TITLE | MODEL | ISSUE DATE |
| SB 5800-22-01 | Automatic Flight Control Systems - FCC Error Code Switches on Maintenance Switch Panel - Re-label Pilot/Copilot Switch Positions | CV5800 | Jan 15/2001 |
| SB CV 5800-23-001 | Communications - Audio and Video Monitoring - CVR Replacement | CV5800 | May 31/2009 |
| SB 5800-23-002 | Replacement of RM-850 Series Radio Management Units (RMUs) with RM-855 Series RMUs | CV5800 | Rev 1 - Oct 18/2013 |
| SB 5800-24-01 | Electrical Power - Essential Circuit Breaker Panel - Replacement of Existing Circuit Breakers | CV5800 SN 276/277/278/ 309 | Jun 13/2008 |
| SB 5800-24-02 | Electrical Power - Control Column Disconnects - Wiring Changes | CV5800 | May 31/2008 |
| SB CV 5800-24-001 | Obsolete Relay Part Numbers NS47E, NS47EK and ND47E | CV5800 | Jul 02/2008 |
| SB 5800-24-003 | Electrical Power - Main Circuit Breaker Panel - Replacement of Strobe Lights Circuit Breaker | CV5800 SN 276/277/278/ 309/343 | Sep 15/2009 |
| SB 5800-24-004 | Inverter INOP Light Change | CV5800 SN 276/277/278/ 309 | Jan 21/2013 |
| SB 5800-24-005 | Installation of Relays for Inverter INOP Announcement (Aircraft S/N 343) | CV5800 SN 343 | Jan 25/2013 |
| SB 5800-31-01 | Indicating/Recording Systems - Cockpit Voice Recorder - Reroute CVR Power Supply Wiring | CV5800 SN 276/278 | Dec 31/2000 |

CONVAIR SERVICE BULLETIN/LETTER INDEX

| | | | |
|------------------------------------|--|---|---------------------|
| SB 5800-31-02 CANCELLED | Indicating/Recording Systems – Flight Data Recorder – Rewire Ground Connections for Heading, Pitch and Roll Attitude | CV5800 | Dec 31/2000 |
| SB 5800-31-03 CANCELLED | Emergency Locator Transmitter (ELT) - Remote Switch Installation | CV5800 | May 31/2002 |
| SB 5800-35-001 | Replacement of Oxygen Regulator | CV5800 SN 279 | Rev 3 - Dec 06/2016 |
| SB 5800-52-002 | Door Warning Panel Modification | CV5800 | Jul 5/2016 |
| SB 5800-53-01 CANCELLED | Inspection of Centre and Aft Main Longerons | CV5800 | Apr 25/2003 |
| SB 5800-55-01 | Relocation of Vortex Generators on Horizontal Stabilizers | CV5800 SN 276/277/278/ 309/343 | Oct 5/2007 |
| SB 5800-79-001 | Replacement of Cockpit Oil Quantity Indicator and Nacelle Oil Calibration Rheostats | CV5800 | Oct 26/2012 |
| SB CV5800-80-001 | Replacement of Moisture Indicator Plug and Placard of Nitrogen Start System | CV5800 | Dec 02/2010 |
| | | | |
| SL 5800-24-001 | DC Generator Control Panel | CV580/580A/ 5800 | Nov 26/2012 |
| SL 5800-31-001 | Tachometer Indicator | CV580/580A/ 5800 | Oct 10/2012 |
| SL 5800-32-001 CANCELLED | NLG Wheel Assembly - Torque Flange Bolts | CV580/5800 | Feb 21/2017 |
| SL 5800-52-002 | Door Warning Panel Modification | CV5800 | Rev 1 – Jul 11/2018 |
| SL 5800-57-001 | Corrosion Inspections | CV580/580A/ 5800 | Sep 11/2013 |
| SL 5800-61-001 | Propeller Feather Switch | CV580/580A/ 5800 | Oct 05/2012 |
| SL 5800-76-001 | Emergency Shutdown Switch | CV580/580A/ 5800 | Jul 22/2013 |