



KF AEROSPACE CONVAIR DIVISION 340/440/640/580/5800 SERVICE BULLETIN/SERVICE LETTER INDEX
NUMERICAL SERVICE BULLETIN/SERVICE LETTER AND TITLE LISTING
(LISTS SERVICE BULLETIN/SERVICE LETTER ISSUED JANUARY 2001 AND ON)

Basic Issue: Oct 19/2018

Rev Date: Jan 29/2025

Prepared by: KF Aerospace Technical Publications



Convair® Division

LIST OF EFFECTIVE PAGES

<u>Page No.</u>	<u>Date</u>	<u>Page No.</u>	<u>Date</u>
I A	Jan 29/2025	35-2	May 4/2020
0-1	Sep 20/2021	52-1	Aug 25/2020
22-1	May 4/2020	53-1	May 4/2020
23-1	May 4/2020	55-1	May 4/2020
24-1	May 4/2020	57-1	May 4/2020
25-1	Sep 20/2021	61-1	May 4/2020
I 27-1	Jan 29/2025	71-1	May 4/2020
31-1	May 4/2020	76-1	May 4/2020
32-1	Sep 20/2021	77-1	Sep 20/2021
I 33-1	Jan 29/2025	79-1	May 4/2020
34-1	Feb 1/2024	80-1	May 4/2020
35-1	May 4/2020	82-1	May 4/2020



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
GENERAL						
SL 340-00-001	Surrender of EASA Validated Convair 340/440 Aircraft Type Certificate A-220	X				Aug 28/2017
SL 340-00-002	Use of Electrostatic Foggers on Aircraft to Combat Covid-19	X	X	X	X	Aug 20/2020
SL 580-00-001	Cancelled			X		Oct 6/2018
SL 580-00-002	New Convair CV580 Maintenance Manual			X		Jan 19/2021



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340	640	580	5800	
		440	DART			
CHAPTER 22 – AUTO FLIGHT						
* SB 5800-22-01	Automatic Flight Control Systems – FCC Error Code Switches on Maintenance Switch Panel – Re-Label Pilot / Copilot Switch Positions				X	Jan 15/2001

* S/Ns 276 and 278



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 23 – COMMUNICATIONS						
SB 5800-23-001	Communications – Audio and Video Monitoring – CVR Replacement				X	May 31/2009
SB 5800-23-002	Replacement of RM-850 Series Radio Management Units (RMU's) with RM-855 Series RMU's				X	Dec 21/2012
						Revision 1, Oct 18/2013

Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 24 – ELECTRICAL POWER						
* SB 340-24-001	Obsolete Relay Part Numbers NS47E, NS47EK and ND47E	X				Jul 02/2008
SB 580-24-001	Obsolete Relay Part Numbers NS47E, NS47EK and ND47E			X		Jul 02/2008
SL 580-24-001	DC Generator Control Panel			X		Nov 26/2012
SL 580A-24-001	DC Generator Control Panel			X		Nov 26/2012
SB 5800-24-001	Obsolete Relay Part Numbers NS47E, NS47EK and ND47E				X	Jul 02/2008
SL 5800-24-001	DC Generator Control Panel				X	Nov 26/2012
SB 580-24-002	Electrical Power, Current Transformer Replacement			X	X	Jul 30/2013
** SB 5800-24-003	Electrical Power – Main Circuit Breaker Panel – Replacement of Strobe Lights Circuit Breaker				X	Sep 15/2009
† SB 5800-24-004	Inverter INOP Light Change				X	Jan 21/2013
SB 5800-24-005	Installation of Relays for Inverter INOP Annunciation (Aircraft S/N 343)				X	Jan 25/2013
† SB 5800-24-01	Electrical Power – Essential Circuit Breaker Panel – Replacement of Existing Circuit Breakers				X	Jun 13/2008
† SB 5800-24-02	Electrical Power – Control Column Disconnects – Wiring Changes				X	May 31/2008

† S/Ns 276, 277, 278 and 309

** S/Ns 276, 277, 278, 309 and 343

* Also applicable to C-131 (Military) series aircraft.



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 25 – EQUIPMENT/FURNISHINGS						
SL 340-25-001	Pacific Scientific Rotary Buckle AD2021-07-13	X	X	X	X	Jun 21/2021
* SB 580-25-001	NAV/GLS and VHF COMM Panels Modification			X		Sep 19/2011

* S/N 002 only.



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 27 – FLIGHT CONTROLS						
* SB 340-27-001	Flight Controls – Elevator Trim Cable Routing – Placard Installation	X	X	X	X	Apr 24/2015
SL 34-27-001	Pin Assembly – Elevator and Rudder Alternate Part Numbers	X	X	X	X	May 22/2024
SB 580-27-002	Rudder Torque Tube Coupling – Crack Inspection			X	X	Jul 18/2018

* Also applicable to C-131 (Military) series aircraft.



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 31 – INSTRUMENTS						
SL 580-31-001	Tachometer Indicator			X		Oct 10/2012
SL 580A-31-001	Tachometer Indicator			X		Oct 10/2012
* SB 5800-31-01	Indicating / Recording Systems – Cockpit Voice Recorder – Reroute CVR Power Supply Wiring				X	Dec 31/2000
SL 5800-31-001	Tachometer Indicator				X	Oct 10/2012

* S/Ns 276 and 278



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 32 – LANDING GEAR						
* SB A340-32-001	Nose Landing Gear (NLG) Upper Drag Strut Inspection at the Down-Latch Lever Attachment Location	X	X	X	X	Nov 28/2013
SB 640(340D) 32-016	Inspection of MLG Axle Inner Surface	X	X	X	X	Feb 10/2005
* SL 340-32-001	MLG Actuator Rigging Placard	X	X			Jun 18/2014
* SL 340-32-002	NLG Down-Latch Rigging	X	X	X	X	Nov 20/2014
SL 340-32-003	NLG Wheel – Alternate Torque Flange Bolts	X		X	X	Apr 15/2020
SL 340-32-004	NLG Wheel – Check Self-Locking Torque on Torque Flange Spline Nuts	X	X	X	X	Sep 20/2020
SL 340-32-005	Recall of 340-8300019-1 Bolts from LOT# 1906200005	X	X	X	X	May 3/2021
SL 580-32-001	Cancelled			X	X	Mar 8/2017

* Also applicable to C-131 (Military) series aircraft.



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 33 – LIGHTS						
SB 340-33-001	Lights – External – Position Lights Replacement	X				Dec 2/2008 Revision 1, Jan 14/2024
SB 580-33-001	Lights – External – Position Lights Replacement			X		Dec 2/2008 Revision 1, Jan 12/2024



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 34 – NAVIGATION						
SB 340-34-001	Alternate Magnetic Compass Installation	X	X	X		Mar 22/2021
SB 5800-34-001	Radio Altimeter System C-Band Filter				X	Oct 10/2023
						Revision 1, Jan 30/2024



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 35 – OXYGEN						
SB 340-35-001	Cancelled	X				Revision 2, Feb 15/2012
SB 440-35-001	Cancelled	X				Revision 2, Feb 15/2012
SB 580-35-001	Cancelled			X		Revision 2, Feb 15/2012
** SB 5800-35-001	Replacement of Oxygen Regulator				X	Sep 12/2011
	** S/Ns 279 only.					Revision 2, Feb 15/2012
						Revision 3, Dec 6/2013
SB 340-35-002	Oxygen Regulator and Altitude Gauge Protector Installation (K260-35000-7 Oxygen System Modification)	X	X	X	X	May 17/2013
						Revision 1, Jul 09/2013
						Revision 2, Jul 29/2013
						Revision 3, Apr 15/2019

Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 35 – OXYGEN (continued)						
* SB 340-35-003	Oxygen Regulator and Altitude Gauge Protector Installation (K260-35000-5 Oxygen System Modification)			X		Jul 09/2013
						Revision 1, Jul 29/2013
						Revision 2, Apr 15/2019

* S/Ns 022, 082, 151 and 160



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 52 – DOORS						
* SB 340-52-001	Exterior Doors – (Yoke Assembly) – Inspection	X	X	X	X	Apr 15/2016
SB 340-52-003	Emergency Exit Door Seal Replacement	X	X	X	X	Jul 31/2020
SB 5800-52-002	Door Warning Panel Modification				X	Jul 05/2016
						Revision 1, Jul 11/2018

* Also applicable to C-131 (Military) series aircraft.



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340	640	580	5800	
		440	DART			
CHAPTER 53 – FUSELAGE						
SB 340-53-001	Nose Landing Gear (NLG) Beam Upper Chord Reinforcement	X	X	X	X	Dec 23/2013

Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 55 – STABILIZERS						
* SB 340-55-001	LH and RH Elevator Skin and Bead Strip Visual Inspection	X	X	X	X	Nov 20/2014
** SB 5800-55-01	Relocation of Vortex Generators on Horizontal Stabilizers				X	Oct 05/2007
SB 580-55-002	Elevator Rear Spar Crack Inspection			X		Jan 5/2015
						Revision 1, Aug 28/2015
* SB 340-55-003	Stabilizers LH and RH Elevator Nose Rib Tee Visual Inspection	X	X	X	X	Nov 20/2014

** S/Ns 276, 277, 278, 309 and 343

* Also applicable to C-131 (Military) series aircraft.



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 57 – WINGS						
* SB 340-57-001	Inspection of Lower Wing Skin for Cracks between WS 5 and WS 6	X	X	X	X	Feb 12/2013
SL 580-57-001	Corrosion Inspections			X		Sep 11/2013
SL 580A-57-001	Corrosion Inspections			X		Sep 11/2013
SL 5800-57-001	Corrosion Inspections				X	Sep 11/2013

* Also applicable to C-131 (Military) series aircraft.



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 61 – PROPELLERS						
SL 580-61-001	Propeller Feather Switch			X		Oct 5/2012
SL 580A-61-001	Propeller Feather Switch			X		Oct 5/2012
SL 5800-61-001	Propeller Feather Switch				X	Oct 5/2012



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340	640	580	5800	
		440	DART			
CHAPTER 71 – POWER PLANT						
SL 580-71-001	QEC Quick Disconnects Modification			X		Nov 24/2016



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 76 – ENGINE CONTROLS						
SL 580-76-001	Emergency Shutdown Switch			X		Jul 22/2013
SL 580A-76-001	Emergency Shutdown Switch			X		Jul 22/2013
SL 5800-76-001	Emergency Shutdown Switch				X	Jul 22/2013



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340	640	580	5800	
		440	DART			
CHAPTER 77 – ENGINE INDICATING						
SL 580-77-001	Turbine Inlet Temperature Indicator Part Numbers			X		Jul 30/2021



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 79 – OIL						
SB 580-79-001	Replacement of Cockpit Oil Quantity Indicator and Nacelle Oil Calibration Rheostats			X		Sep 06/2012
SB 5800-79-001	Replacement of Cockpit Oil Quantity Indicator and Nacelle Oil Calibration Rheostats				X	Oct 26/2012



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340 440	640 DART	580	5800	
CHAPTER 80 – STARTING						
SB 580-80-001	Replacement of Moisture Indicator Plug and Placard of Nitrogen Start System			X		Dec 02/2010
* SB 580A-80-001	Replacement of Moisture Indicator Plug and Placard of Nitrogen Start System			X		Dec 02/2010
SB 5800-80-001	Replacement of Moisture Indicator Plug and Placard of Nitrogen Start System				X	Dec 02/2010

* All Convair CV580A aircraft.



Convair® Division

SERVICE BULLETIN/LETTER NUMBER	TITLE	MODELS AFFECTED				ISSUE DATE
		340	640	580	5800	
		440	DART			
CHAPTER 82 – WATER INJECTION						
SB 640(340D) 82-004	Cancelled		X			Nov 25/2004