



KELOWNA **Flightcraft** LTD.

5655 Airport Way Kelowna Airport, Kelowna, B.C., Canada, V1V 1  
Ph. 250-491-5568 fax 250-491-5518 E-M [billd@flightcraft.ca](mailto:billd@flightcraft.ca)

## CONVAIR® DIVISION

# SERVICE ENGINEERING ALERT NOTICE

**SEAN-003-2002**

**DATE: April,10, 2002**

AIRCRAFT AFFECTED: All Convair 340/440/640/580/5800

SUBJECT: Compliance with Airworthiness Directive 92-06-06 General Dynamics.

PURPOSE: The purpose of this Service Engineering Alert Notice is to inform registered owners/operators of the requirements of AD92-06-06.

BACKGROUND: AD 92-06-06 states that all inspection results (negative or positive) must be reported to General Dynamics in accordance with the instructions in the SID.

Since the AD was developed the Convair Division has been sold by General Dynamics to Tracor and resold by Tracor to Kelowna Flightcraft Ltd.

Recommendation: It is recommended that all inspection results whether negative or positive be forwarded to the address listed below.

Kelowna Flightcraft Convair® Division,  
5655 Airport Way, Kelowna Airport,  
Kelowna B.C. Canada, V1V 1S1

Ph. 250-491 5568, Fax 250 491 5518, E-M [billd@flightcraft.ca](mailto:billd@flightcraft.ca)

Bill De Meester  
Manager;  
Convair® Division

